


File Nr. 3875

STATINTL

17 December 1958

STATINTL



Dear Don:

STATINTL

Reference your letter of 9 December 1958 and telephone conversation with [redacted] concerning shaft bearings.

No prints of this bearing are available at this depot. We have asked Sid Brewer to try and locate one for you at his location.

The specifications of this bearing are listed as follows in the Air Force Stock List:

Bore Diameter Inches - .3750
Outside Diameter Inches - .9063
Over-all width Inches - .3125

Attached to this letter are amendments to our Production List 59-8 and to Purchase Request 8-13-15.

The production list was amended to change the stock number and to increase the quantity of bearings being procured. Purchase Request Number 8-13-15 was amended to add a stock number for the boxes and also to give coverage for the addition of pressure and vacuum release valves.

We have been asked by the field people to identify the lower shaft bearing on the lighting mixer supplied to us on Contract MF-EQ-6081. Please forward any information you may have for this bearing and we will attempt to identify it with an Air Force number.

Sincerely,

STATINTL



2 Incls

1. P/L 59-8 Amend #1 (2 copies)
2. P/R 8-13-15 Amend #1 (2 copies)